



1 / 2 6
FIG. 1




2 / 2 6

FIG. 2




3 / 2 6

FIG. 3




4 / 2 6

FIG. 4



5 / 26

FIG. 5



6 / 2 6

FIG. 6



7 / 26

FIG. 7






FIG. 8




9 / 26

FIG. 9




10 / 26

FIG. 10




1 1 / 2 6

FIG. 1 1




1 2 / 2 6

FIG. 1 2




1 3 / 2 6

FIG. 1 3



1 4 / 2 6

FIG. 1 4







FIG. 1 5

1 6 / 2 6

FIG. 1 6

(a)



(b)





FIG. 1 7

FIG. 18

Amounts of Ni and Pb leached from entirely surface plated test piece




FIG. 19

Amounts of Ni and Pb leached from partially surface-plated test piece




FIG. 20





FIG. 2 1








FIG. 2 2

23 / 26

FIG. 2 3









FIG. 2.5

26 / 26

FIG. 26

(a)



(b)

